

Amended sheet 6 (claims 1-10) need NOT be entered in light of new claims 11-20 herein below.

Please ADD new claims 11-20 reading as follows:

11. (new) Visor assembly comprising an outer shield and an inner shield spaced therefrom, which inner shield is located within the periphery of the outer shield, wherein mechanical fixing means are arranged between the two shields for fixing the latter with respect to <sup>the former</sup> ~~one another~~, said outer shield being provided with means for fixing ~~the latter~~ <sup>the inner shield</sup> with respect to one another, said outer shield being provided with means for fixing to a further component, such as a helmet or goggles frame, wherein a seal/spacer extending around the periphery of said inner shield is fitted between the outer shield and inner shield, said seal/spacer being stuck to the inner shield and fitted detachably against said outer shield.

12. (new) Visor assembly according to Claim 11, wherein a gas/air chamber is delimited between the inner shield and outer shield and wherein the internal width of said chamber is at least 2 mm.

13. (new) Visor according to Claim 11, wherein said mechanical fixing means comprise pins fitted on the outer shield which interact with recesses made in the inner shield.

14. (new) Visor assembly according to Claim 11, wherein said seal/spacer is made of

silicone material.

15. (new) Visor assembly according to Claim 11, wherein said outer shield is made of polycarbonate.

16. (new) Visor assembly according to Claim 11, wherein said inner shield is made of heat-treated cellulose acetate material.

17. (new) Visor assembly according to Claim 11, wherein said mechanical fixing means comprise a seat in said outer shield which at least partially corresponds to the shape of said inner shield.

18. (new) Visor assembly according to Claim 11, wherein said inner shield is made of cellulose propionate material.

19. (new) Visor assembly according to Claim 18, wherein said inner shield is provided on one side with a coating that counter acts misting up.

20. (new) Visor assembly according to Claim 18, wherein said inner shield is provided on one side with a coating which improves scratch resistance.

---